

Celebrating Thirty-six Years of Experience & Integrity

Scotts Valley Water District

Sequoia Exterior Coating Analysis



Mr. Nate Gillespie
Operations Manager
2 Civic Center Drive
Scotts Valley, CA 95066

Prepared By

Mr. Ed Darrimon National Association of Corrosion Engineers Inspector Number #106 July 6, 2023

Introduction

At the request of the Scotts Valley Water District, Bay Area Coating Consultants, Inc. (BACC) conducted condition assessment inspection the exterior of Sequoia reservoir. The reservoir is an AWWA D-100 welded carbon steel tank. BACC was requested to perform an exterior coating assessment. The exterior shell was overcoated within the past five years.

This report is prepared on the basis of noted field investigations and the review of existing information furnished by Scotts Valley Water District. The conclusions and recommendations contained within this report are those determined by the coating inspection consultant and are consistent with the best practices identified by AWWA, NACE, ASTM and SSPC.

Background Information				
Location:	Scotts Valley, CA.			
Project Engineer:	Mr. Nate Gillespie			
Identification:	No Identification			
Year Built: 1983				
Diameter: 85'				
Height: 32'				
Builder: Trsco Tank				
Capacity: 1.25 MG.				
Type of Lining:	Ероху			
Exterior coating.:	Unknown			
Cathodic Protection:	Yes			

Inspected By: Mr. Ed Darrimon

N.A.C.E. Certified Inspector #106



The exterior shell plate coating is in good condition.



Detachment of over coat at floor plate extension



Vegetation growth at base of tank



No caulking at interface between foundation and tank floor plate extension





Center Vent

Failed fractured roof plate coating.



The coating failed, and uniform corrosion is coming through the existing roof plate coating.

Findings

The exterior of the shell has been overcoated within the past five years. The exterior roof plates were not coated. The existing coating has totally failed. The coating has become brittle and has fractured down to the steel substrate. No isolated or exfoliation corrosion was noted. The roof plates are exhibiting large areas where the base metal is rusting. This type of corrosion is called uniform corrosion in which the steel corrodes evenly. Spot, or exfoliation concentrates in an area that leads to a more severe type of corrosion and metal isolated metal loss in a concentrated area. The exterior roof plate coating is completely failed and will require abrasive blasting and application of a new coating system.

The coating on the shell plates looks to be in good condition. We are witnessing minor peeling along the tub ring floor plate extension. Amy vegetation growth should always be maintained at the base of the tank.

Recommendations

The roof plate should be abrasive blasted to SSPC/SpNo.10 near white metal. I would recommend wet abrasive blasting using a water ring. All the vents will require protective covers installed each day and removed at the end of the day to prevent the tank from implosion during a rapid drawdown of the rank. The material would to HEPA filter material. A prime coat with a stripe coat of the welds with something like PPG/Ameron Amerlock 2 surface tolerant epoxy. Then a coat of PPG/PSX 700 poly siloxane finish coat. There are better anode covers and the existing covers should be replaced with a rubber handhold grommet which will help with edge corrosion and any water intrusion into the tank. The gap at the interface between the concrete slab and the floor plate extension should be caulked something like Sika 2-C Non sag to prevent water intrusion from entering the bottom of the tank floor plates. The minor areas at the bottom of the tub ring floor plate extension should be touched up with the same system applied to the roof. If you are going to rehabilitate the roof coating system, the outer vents could use new fiber glass covers to protect from water intrusion through the vent screens. The center vent is in good condition.





C/P Handhold Gasket

Exposed vent screens

Please call if you have any questions or if you want to further discuss the information contained in this report.

Respectfully submitted,

Please call if you have any questions or if you want to further discuss the information contained in this proposal.

Respectfully Submitted,

Ed Darrimon President

Bay Area Coating Consultants, Inc.


edarrimon@bayareacoating.com www.bayareacoating.com





BACC Safety and Drug Testing Compliance Partners













CONSTRUCTION PLANS FOR A 1.25 MILLION GALLON WATER TANK FOR STEKOLL DEVELOPMENT CORPORATION AT SCOTTS VALLEY.

DRAWING RECORD DRAWING

COV	ER SHI	EET	
SCALE:	APPROVED BY:		DRAWN BY AMD
DATE: 5-18-83			REVISED
SC	OTTS	VALL	EY.
TRUSCO	TẠNK,	INC.	DRAWING NUMBER


SANTA BARBARA


STATE OF CALIFORNIA

· RIVERSIDE

SAN CLEMENTE

SAN DIEGO







SW


OVERFLOW BRACKET DETAILS

- 2'-8" - 1'-6" -






NOTE: LOCATION OF TANK ACCESSORIES, INLET & OUTLET LINES ARE APPROXIMATE. FINAL LOCATION WILL BE DETERMINED IN THE FIELD DURING CONSTRUCTION BY CUSTOMER.



(D) (B) (D)

	MATERIAL LIST	Constitution of the second	
NO.	DESCRIPTION	MATERIAL	NO. REQ'D
	CONE 1/4" P x 31 1/2" 1.D. x 12 1/4" 1.D. x 18" HIGH	A36	
2	12" SCH 40 PIPE x 26-0"19.	A53-B	1
3	12" SCH 40 L.R. 90° ELL	A 234	1 lens
4	12" SCH 40 PIPE x 2-4" LG.	A53-B	
5	1/4" PL × 26" × 2-5" 4G.	A36	3
6	WELD NECK FF FLANGE 150 LB x 12"	A181	3
7	3/8" PL x 17" O.D. x 12 3/4" 1.D. x 321/2" LG.	A36	3
8	12" SCH 40 PIPE x 1-6" LG.	A53-B	1
9	12" SCH 40 PIPE x 1-2" LG.	A53-B	la barre
10	1/2" SCH 40 x 6" LG G.I. TANK NIPPLE	A120	1
11	1/2" THREADED PIPE CAP GALV. IRON	A-120	1
12	1" SCH. 40 x 6" LG. GALV. IRON PIPE T.O.E.	A120	2
13	I" FEMALE THREADED GATE VALVE CRANE No.437	BRONZE	2
14	11/2" 90° STREET ELBOW - GALV. IRON	A120	1
15	I" STREET TEE WITH PLUG , GALV. IRON	A120	2
16	1/2" ASPHALT IMPREG EXPANSION JOINT MATERIAL - 4' X 10' STANDARD SHEET - Out GB PCS. Min. @ 10" X 48" w 15/16" Trim.	ASTM D1751.78	6

ANGLE	STRAP DIST.
90°0′0″	66'-913/32"
45° 0′0″	33'-4"/16"
45° 0'0"	33'-41/6"
37° 0′ 0″	27'-5 132"
8° 5′ 9″	6'-0"
5° 23′ 26″	4'-0"
5° 23′ 26″	4'-0"
2° 41′ 43″	2'-0"
10° 6′ 26"	7-6"
6° 3′ 52″	4'-6"
15° 15′ 58″	11-315/6"
25° 0′ 0″	18'-65/8"
600'0"	4'-576"
14 0 0 0"	10'-4 21/32"
45° 0' 0"	33'-41/6"
	90°0'0" 45°0'0" 45°0'0" 37°0'0" 8°5'9" 5°23'26" 2°41'43" 10°6'26" 6°3'_52" 15°15'58" 25°0'0" 6°0'0" 14°0'0"



RECORD

SC. DA

TANK PLAN & DETAILS

BCALE: AS Shown APPROVED BY: DRAWN BY AMD

SCOTTS VALLEY

RUSCO TANK, INC. 1 OF 9

4 PRINTED ON NO. 1000H CLEARPI

